



MICROCHIP PIC18F2458/2553/4458/4553

PIC18F2458/2553/4458/4553 Rev. B5 Silicon Errata

The PIC18F2458/2553/4458/4553 Rev. B5 parts you have received conform functionally to the Device Data Sheet (DS39887B), except for the anomalies described below. Any Data Sheet Clarification issues related to the PIC18F2458/2553/4458/4553 will be reported in a separate Data Sheet errata. Please check the Microchip web site for any existing issues.

Note: The "PIC18F2458/2553/4458/4553 Data Sheet" is supplemented by the "PIC18F2455/2550/4455/4550 Data Sheet" (DS39632). PIC18F2458/2553/4458/4553 features and specifications that are shared with the PIC18F2455/2550/4455/4550 devices are documented in the "PIC18F2455/2550/4455/4550 Data Sheet".

The following silicon errata apply only to PIC18F2458/2553/4458/4553 devices with these Device/Revision IDs:

Part Number	Device ID	Revision ID
PIC18F2458	10 1010 011	0 0101
PIC18F2553	10 1010 010	0 0101
PIC18F4458	10 1010 001	0 0101
PIC18F4553	10 1010 000	0 0101

The Device IDs (DEVID1 and DEVID2) are located at addresses 3FFFFEh:3FFFFFh in the device's configuration space. They are shown in hexadecimal in the format "DEVID2 DEVID1".

All of the issues listed here will be addressed in future revisions of the PIC18F2458/2553/4458/4553 silicon.

TABLE 1: EXAMPLE SPI MODE REQUIREMENTS (SLAVE MODE TIMING)

Param No.	Symbol	Characteristic	Min	Max	Units	Conditions
70	TssL2sCH, TssL2sCL	\overline{SS} ↓ to SCK ↓ or SCK ↑ Input	3 Tcy	—	ns	

1. Module: MSSP

In SPI Slave mode with slave select enabled (SSPM<3:0> = 0100), the minimum time between the falling edge of the \overline{SS} pin and first SCK edge is greater than specified in parameter 70 in Table 28-17 and Table 28-18 of the "PIC18F2455/2550/4455/4550 Data Sheet" (DS39632). The updated specification is shown in bold in Table 1.

The minimum time between \overline{SS} pin low and an SSPBUF write is also 3 Tcy. If the falling edge of the \overline{SS} pin occurs greater than 3 Tcy, before the first SCK edge or loading SSPBUF, the peripheral will function correctly. Also, if SSPBUF is written prior to the \overline{SS} pin going low, the peripheral will function correctly.

Work around

None.

Date Codes that pertain to this issue:

All engineering and production devices.

PIC18F2458/2553/4458/4553

2. Module: MSSP

With MSSP in SPI Master mode, $F_{osc}/64$ or Timer2/2 clock rate and $CKE = 0$, a write collision may occur if SSPBUF is loaded immediately after the transfer is complete. A delay may be required after the MSSP Interrupt Flag bit, SSPIF, is set or the Buffer Full bit, BF, is set and before writing SSPBUF. If the delay is insufficiently short, a write collision may occur as indicated by the WCOL bit being set.

Work around

Add a software delay of one SCK period after detecting the completed transfer and prior to updating the SSPBUF contents. Verify the WCOL bit is clear after writing SSPBUF. If the WCOL is set, clear the bit in software and rewrite the SSPBUF register.

Date Codes that pertain to this issue:

All engineering and production devices.

3. Module: ECCP (PWM Mode)

When configured for half-bridge operation with dead band ($CCPxCON\langle 7:6 \rangle = 10$), the PWM output may be corrupted for certain values of the PWM duty cycle. This can occur when these additional criteria are also met:

- A non-zero dead-band delay is specified ($PDC6:PDC0 > 0$)
- The duty cycle has a value of 0 through 3, or $4n + 3$ ($n \geq 1$)

Work around

None.

Date Codes that pertain to this issue:

All engineering and production devices.

4. Module: EUSART

In Synchronous Master mode, while transmitting the Most Significant data bit, the data line (DT) may change state before the bit finishes transmitting. If the receiver samples the data line later than 0.5 bit times + $1.5 T_{CY}$ (of the master) after the starting edge of the MSb, the bit may be read incorrectly.

Work around

None.

Date Codes that pertain to this issue:

All engineering and production devices.

5. Module: ADC

When the A/D clock source is selected as 2 TOSC or RC ($ADCS2:ADCS0 = 000$ or $x11$), the EIL (Integral Linearity Error) and EDL (Differential Linearity Error) may exceed the data sheet specification at codes 2047, 2048 and 2049 only.

Work around

Select a different A/D clock source (4 TOSC, 8 TOSC, 16 TOSC, 32 TOSC, 64 TOSC) and avoid selecting the 2 TOSC or RC modes.

Date Codes that pertain to this issue:

All engineering and production devices.

6. Module: Electrical Characteristics (BOR)

Certain operating conditions can move the effective Brown-out Reset (BOR) threshold outside of the range specified in the electrical characteristics of the device data sheet (parameter D005).

The BOR threshold has been observed to increase with high device operating frequencies, some table read operations and heavy loading on the USB voltage regulator. When all of these conditions are present, BOR has been observed with V_{DD} 20 percent higher than the V_{BOR} value specified for a given $\langle BORV1: BORV0 \rangle$ setting.

The BOR threshold may decrease under other conditions, such as during Sleep, where it may not occur until V_{DD} is 120 mV below the specified minimums.

Work around

None.

Date Codes that pertain to this issue:

All engineering and production devices.

7. Module: MSSP (SPI Slave)

If configured in SPI Slave mode, the MSSP may not successfully recognize data packets generated by an external master processor. This applies to all SPI Slave modes (CKE/CKP = 1 or 0), whether or not slave select is enabled (SSPM3:SSPM0 = 010x).

Work around

Insert a series resistor between the SPI master Serial Data Out (SDO) and the corresponding SPI slave Serial Data In (SDI) input line of the microcontroller. The required value for the resistor varies with the application system's characteristics and the process variations between the microcontrollers.

Experimentation and thorough testing are encouraged.

Date Codes that pertain to this issue:

All engineering and production devices.

8. Module: MSSP

When operated in I²C™ Master mode, the I²C baud rate may be somewhat slower than predicted by the following formula:

$$I^2C \text{ Master mode, clock} = \frac{F_{OSC}}{4 \bullet (SSPADD + 1)}$$

Work around

If the target application is sensitive to the baud rate and requires more precision, the SSPADD value can be adjusted to compensate.

If this work around is going to be used, it is recommended that the firmware first check the Revision ID by reading the DEVID1 value at address 3FFFFEh. Silicon revisions B6 and B7 will match the I²C baud rate predicted by the given formula.

Date Codes that pertain to this issue:

All engineering and production devices.

PIC18F2458/2553/4458/4553

REVISION HISTORY

Rev A Document (5/2007)

Initial release of this document. Silicon issues 1-2 (MSSP), 3 (ECCP – PWM Mode), 4 (EUSART) and 5 (ADC).

Rev B Document (3/2008)

Added silicon issue 6 Electrical Characteristics (BOR).

Rev C Document (4/2008)

Added silicon issue 7 (MSSP – SPI Slave).

Rev D Document (9/2008)

Added silicon issue 8 (MSSP).

Note the following details of the code protection feature on Microchip devices:

- Microchip products meet the specification contained in their particular Microchip Data Sheet.
- Microchip believes that its family of products is one of the most secure families of its kind on the market today, when used in the intended manner and under normal conditions.
- There are dishonest and possibly illegal methods used to breach the code protection feature. All of these methods, to our knowledge, require using the Microchip products in a manner outside the operating specifications contained in Microchip's Data Sheets. Most likely, the person doing so is engaged in theft of intellectual property.
- Microchip is willing to work with the customer who is concerned about the integrity of their code.
- Neither Microchip nor any other semiconductor manufacturer can guarantee the security of their code. Code protection does not mean that we are guaranteeing the product as "unbreakable."

Code protection is constantly evolving. We at Microchip are committed to continuously improving the code protection features of our products. Attempts to break Microchip's code protection feature may be a violation of the Digital Millennium Copyright Act. If such acts allow unauthorized access to your software or other copyrighted work, you may have a right to sue for relief under that Act.

Information contained in this publication regarding device applications and the like is provided only for your convenience and may be superseded by updates. It is your responsibility to ensure that your application meets with your specifications. MICROCHIP MAKES NO REPRESENTATIONS OR WARRANTIES OF ANY KIND WHETHER EXPRESS OR IMPLIED, WRITTEN OR ORAL, STATUTORY OR OTHERWISE, RELATED TO THE INFORMATION, INCLUDING BUT NOT LIMITED TO ITS CONDITION, QUALITY, PERFORMANCE, MERCHANTABILITY OR FITNESS FOR PURPOSE. Microchip disclaims all liability arising from this information and its use. Use of Microchip devices in life support and/or safety applications is entirely at the buyer's risk, and the buyer agrees to defend, indemnify and hold harmless Microchip from any and all damages, claims, suits, or expenses resulting from such use. No licenses are conveyed, implicitly or otherwise, under any Microchip intellectual property rights.

Trademarks

The Microchip name and logo, the Microchip logo, Accuron, dsPIC, KEELOQ, KEELOQ logo, MPLAB, PIC, PICmicro, PICSTART, rfPIC and SmartShunt are registered trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.

FilterLab, Linear Active Thermistor, MXDEV, MXLAB, SEEVAL, SmartSensor and The Embedded Control Solutions Company are registered trademarks of Microchip Technology Incorporated in the U.S.A.

Analog-for-the-Digital Age, Application Maestro, CodeGuard, dsPICDEM, dsPICDEM.net, dsPICworks, dsSPEAK, ECAN, ECONOMONITOR, FanSense, In-Circuit Serial Programming, ICSP, ICEPIC, Mindi, MiWi, MPASM, MPLAB Certified logo, MPLIB, MPLINK, mTouch, PICkit, PICDEM, PICDEM.net, PICtail, PIC³² logo, PowerCal, PowerInfo, PowerMate, PowerTool, REAL ICE, rfLAB, Select Mode, Total Endurance, UNI/O, WiperLock and ZENA are trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.

SQTP is a service mark of Microchip Technology Incorporated in the U.S.A.

All other trademarks mentioned herein are property of their respective companies.

© 2008, Microchip Technology Incorporated, Printed in the U.S.A., All Rights Reserved.

 Printed on recycled paper.

QUALITY MANAGEMENT SYSTEM
CERTIFIED BY DNV
== ISO/TS 16949:2002 ==

Microchip received ISO/TS-16949:2002 certification for its worldwide headquarters, design and wafer fabrication facilities in Chandler and Tempe, Arizona; Gresham, Oregon and design centers in California and India. The Company's quality system processes and procedures are for its PIC® MCUs and dsPIC® DSCs, KEELOQ® code hopping devices, Serial EEPROMs, microperipherals, nonvolatile memory and analog products. In addition, Microchip's quality system for the design and manufacture of development systems is ISO 9001:2000 certified.



WORLDWIDE SALES AND SERVICE

AMERICAS

Corporate Office

2355 West Chandler Blvd.
Chandler, AZ 85224-6199
Tel: 480-792-7200
Fax: 480-792-7277
Technical Support:
<http://support.microchip.com>
Web Address:
www.microchip.com

Atlanta

Duluth, GA
Tel: 678-957-9614
Fax: 678-957-1455

Boston

Westborough, MA
Tel: 774-760-0087
Fax: 774-760-0088

Chicago

Itasca, IL
Tel: 630-285-0071
Fax: 630-285-0075

Dallas

Addison, TX
Tel: 972-818-7423
Fax: 972-818-2924

Detroit

Farmington Hills, MI
Tel: 248-538-2250
Fax: 248-538-2260

Kokomo

Kokomo, IN
Tel: 765-864-8360
Fax: 765-864-8387

Los Angeles

Mission Viejo, CA
Tel: 949-462-9523
Fax: 949-462-9608

Santa Clara

Santa Clara, CA
Tel: 408-961-6444
Fax: 408-961-6445

Toronto

Mississauga, Ontario,
Canada
Tel: 905-673-0699
Fax: 905-673-6509

ASIA/PACIFIC

Asia Pacific Office

Suites 3707-14, 37th Floor
Tower 6, The Gateway
Harbour City, Kowloon
Hong Kong
Tel: 852-2401-1200
Fax: 852-2401-3431

Australia - Sydney

Tel: 61-2-9868-6733
Fax: 61-2-9868-6755

China - Beijing

Tel: 86-10-8528-2100
Fax: 86-10-8528-2104

China - Chengdu

Tel: 86-28-8665-5511
Fax: 86-28-8665-7889

China - Hong Kong SAR

Tel: 852-2401-1200
Fax: 852-2401-3431

China - Nanjing

Tel: 86-25-8473-2460
Fax: 86-25-8473-2470

China - Qingdao

Tel: 86-532-8502-7355
Fax: 86-532-8502-7205

China - Shanghai

Tel: 86-21-5407-5533
Fax: 86-21-5407-5066

China - Shenyang

Tel: 86-24-2334-2829
Fax: 86-24-2334-2393

China - Shenzhen

Tel: 86-755-8203-2660
Fax: 86-755-8203-1760

China - Wuhan

Tel: 86-27-5980-5300
Fax: 86-27-5980-5118

China - Xiamen

Tel: 86-592-2388138
Fax: 86-592-2388130

China - Xian

Tel: 86-29-8833-7252
Fax: 86-29-8833-7256

China - Zhuhai

Tel: 86-756-3210040
Fax: 86-756-3210049

ASIA/PACIFIC

India - Bangalore

Tel: 91-80-4182-8400
Fax: 91-80-4182-8422

India - New Delhi

Tel: 91-11-4160-8631
Fax: 91-11-4160-8632

India - Pune

Tel: 91-20-2566-1512
Fax: 91-20-2566-1513

Japan - Yokohama

Tel: 81-45-471- 6166
Fax: 81-45-471-6122

Korea - Daegu

Tel: 82-53-744-4301
Fax: 82-53-744-4302

Korea - Seoul

Tel: 82-2-554-7200
Fax: 82-2-558-5932 or
82-2-558-5934

Malaysia - Kuala Lumpur

Tel: 60-3-6201-9857
Fax: 60-3-6201-9859

Malaysia - Penang

Tel: 60-4-227-8870
Fax: 60-4-227-4068

Philippines - Manila

Tel: 63-2-634-9065
Fax: 63-2-634-9069

Singapore

Tel: 65-6334-8870
Fax: 65-6334-8850

Taiwan - Hsin Chu

Tel: 886-3-572-9526
Fax: 886-3-572-6459

Taiwan - Kaohsiung

Tel: 886-7-536-4818
Fax: 886-7-536-4803

Taiwan - Taipei

Tel: 886-2-2500-6610
Fax: 886-2-2508-0102

Thailand - Bangkok

Tel: 66-2-694-1351
Fax: 66-2-694-1350

EUROPE

Austria - Wels

Tel: 43-7242-2244-39
Fax: 43-7242-2244-393

Denmark - Copenhagen

Tel: 45-4450-2828
Fax: 45-4485-2829

France - Paris

Tel: 33-1-69-53-63-20
Fax: 33-1-69-30-90-79

Germany - Munich

Tel: 49-89-627-144-0
Fax: 49-89-627-144-44

Italy - Milan

Tel: 39-0331-742611
Fax: 39-0331-466781

Netherlands - Drunen

Tel: 31-416-690399
Fax: 31-416-690340

Spain - Madrid

Tel: 34-91-708-08-90
Fax: 34-91-708-08-91

UK - Wokingham

Tel: 44-118-921-5869
Fax: 44-118-921-5820